


090-040-00130 X2 / SX2 Gas Strut Conversion Kit for Tilting Column

Hole drilling diagram



Parts List

No.	Description	Qty
1	Gas Strut	2
2	Connector Bar	2
3	Left Head Block	1
4	Right Head Block	1
5	M5x12mm Hex Socket Head Screw	4
6	M6x25mm Hex Socket Head Screw	4